

Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon,

HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786

info@asiatextileinspections.com www.asiatextileinspections.com

Date:	Report Numbe	er:		Page 1 of 4			
	GARM	ENT INS		TION REPORT			
Buyer:			PO#				
Agent			L/C #	ŧ			
Supplier :							
Manufacturer							
Product Description: Pamela (Zip Trac		d), Fen M					
Style/Code: Pamela/ortalio/vadar/rotty			Order Quantity: 468/1168/3041/2330 Pcs (Total 7007 Pcs)				
Style/Code : Pamela/ortalio/vadar/rotty				Declared Qty. 468/1168/3041/2330 (7007 pcs) Status: 100% finished, but some are not packed into carton(Total 431 cartons)			
Style/Code:				ared Qty. Status:			
Inspection Type Performed: FRI			Inspe	ection Date:			
Inspection Location:							
INSPECTION CONCLUSION (In compa	arison to principa	al's instru	ction 8	, reference sample, as available)			
	Conform	No		Tereferios sampie, as available)			
	0011101111	Confo	-				
Quantities submitted for inspection:		☑		Some goods are not packed into carton, final qtty may have difference with Packing list			
Style, material, color:	V						
Workmanship appearance/functioning	: 📗			AQL 2.5/4.0 Level II, see point 2.0 at page 02			
Packing:	V						
Marking/label:	V						
Measurements/field tests :				Some size are slight over tolerance(see attached sheets)			
General observation: Reservation: 1. Style Vadar have som hem wavy, etc, mill already start to ref 2. Goods have some thread end uncle	inish this style,	other 3 st	yle no				
OVERALL INSPECTION CONCLUSIO	N: ☐ CON	NFORM		☑ NOT CONFORM (Qty, AQL and Measureaments)			
Follow up action: (as applicable) () Inspection certified will be issued () Inspection certified will be issued a () Additional services: () Loading s Samples drawn by: For Lab testing: For re Or reason for not taking samples: INSPECTION METHOD APPLIED: Standard: AQL 2.5 (Major) / 4.0 (Minor)	supervision () S	Stuffing su <u>fective)</u> F	ıpervi				

Sample size inspected: 200 pcs. Sample Selection formula: Square root basis

No. of Cartons Selected: 25 cartons. Samples selected from package numbers: (bulk portion) 9,10,11,21,23,30,31,35,36, 41,44,

77,106,195,196,197, 198,232,260,295, 296, action factory portion 12,15,19,22



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon,

HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786

info@asiatextileinspections.com www.asiatextileinspections.com

Date:	Report Number:						of 4
1.PRODUCT CONFORMITY:							
1.1 Style Conformity:	☑ yes	□no	[] no referen	ce sample / sp	pecification ava	ilable	
1.2 Material Conformity:	☑ yes	no	[] no reference sample / specification available				
1.3 Color Conformity:	☑ yes ☐ no [] no reference sample / specification available						
Reference sample provided	from pri	ncipal		r rom manufacturer			
				_		: <i>t</i>	
2. WORKMANSHIP APPEARAI	of from sup NCE / FUNCT		ECTION FINDING		abie (explanatio	on if necessary)	
Dofo	ctive samples			Critical	Major	Minor	
Defect from style Vadar:	ctive samples	•		Chilcai	iviajoi	IVIIIIOI	
Wrong sewing effect					02		
Serious unclear thread end					01		
Visible white stitch of back side	<u> </u>				05		
Slight visible white stitch of back						07	
Oil stain		01	07				
			01				
Hem wavy Unsecured stitch							
Thread end					02	06	
Defect from style : Ortatio							
Color yarn						01	
Wavy seam (Puckering)					01		
Defect from Style : Pamela							
Zip hard to run					01		
Hem width size (relaxed) too si	mall(short 4cn	n)			01		
Defect from Style: Rotty							
Not found any serious defect e	xcept few thre	ad end					
			Total Defects :		15	14	
			mum allowed :		10	14	
Requested AQL							
Critical defective maximum a	llowed		Within AQL	Four	nd	☐ beyond	ΔΟΙ
Major defective maximum alle		Four	□ beyond if beyond is a second is a secon				
Minor defective maximum alle	·						
Reservation: The selected carto			Within AQL use the supplier			beyond bieces.	



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon,

485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

)

Date:]	Page 3 of 4						
3. PRODUCT-SPECIFIC C	HECKS ON	REDUCED S	SAMPLE SIZI	E (as applicable	e for specific product / or	rder)		
Size measurement on 40 sub	-samples:	ges	☑ no (p	ols. see attached	d measurement sheets)	[] actual finding		
Measurement Point	Size R	ef. Sample	Spec.	Tolerance	Deviation/ Finding	Sample(s)		
Carton size: 53x37x38, 60x38 4.1. Individual packing Conference 4.2. Inner packing conformity 4.3. Export packing conformit 4.4. Packing assortment 'C	ormity:	⊻ yes ⊻ yes	□ no □ no □ no			() ()		
Carton No.	_				Colour Deviation(+ / - sa			
Reservation: As most carto 5. MARKING / LABEL: There are 4 different shipping	-		-	-	cking goods. It may c	ause mistake.		
Supra Distribution Ltd, 2758 Rupert Street, Vancouver, Canada V5M 3T7	church International Ltd, 1 C, Tera40, Auriel Drive, Gree 500U, UK 1991 AW07 BUK 1: 15.5 KOS 14 KGS	Un - Un R	church International Ltd. td., Tera40, Auriol Drivo, G. 36 00U, UK anger ANOT Action Factor SW: 14 K65 NW: 12.8 KGS	Caselle	ribution, Via 1 zze 98, 37060, Di Sommacamf gna, Verona, Italy XWO7 Blue 14 KG5 12.6 KGS	()		
5.2. Shipping mark conformity	/: ☑ yes	☐ no				()		
5.3. Other marks:	ges	☑ no				()		
5.3.1 Side mark conformity:	☑ yes	no				()		
5.3.2 Main label:	☑ yes	☐ no				()		



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon,

HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786

info@asiatextileinspections.com www.asiatextileinspections.com

Date:	Report Number			er:			Page ·	4 of 4
5.3.3 Care label:	V	yes	no	-				_ ()
5.3.4 Composition label:	V	yes	no	-				_ ()
5.3.5 Size label	V	yes	no	-				_ ()
5.3.6 Country origin label:] yes	☑ no	-				_ ()
5.3.7 Hangtag:	\checkmark	yes	no	-				_ ()
5.3.8 Polybag printing/ label:	: [] yes	☑ no	-				_ ()
5.3.9 Inner box printing / laboration	el:] yes	☑ no	-				_ ()
5.3.10 Other Label] yes	☑ no	-				_ ()
6. INFORMATIVE OBSERV Inspection Environment:	ATIONS	S :						
Lighting:	☐ Day	light		\checkmark	Room lighting	☑ Sufficient ☐ Insufficien	nt 🗌 Other :	
Inspection place:	☑ Factory workshop:		nop:		Warehouse	☐ Others :		
Inspection done on:	☑ Tabl	le			Top of cartons	☐ Others :		
Cleanliness:	☑ Clea	an			Dirty	☐ Others :		
Weather condition:	☐ Rair	ny		\checkmark	Dry	☐ Others :		
7. LOADING SUPERVISION	۷:							
Performed on Schedule forATI Seal no.:						✓ Not required		

8. ATTACHMENTS: Measurement sheets, Photo report.