

Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon,

HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786

info@asiatextileinspections.com www.asiatextileinspections.com

Date: Report Number:					Page 1 of 4			
	HON	IE TEXTILE	E INS	PEC1	TION REPORT			
Buyer:					O #			
Agent:				/C #				
Supplier:								
Manufacturer:								
	ant 15	x21cm Do	iche	70x1′	30cm, Servt1 50x100cm, DB1 100x150cm)			
					Order Qty: Gant 3036pcs, Douche 1908 pcs, Servt1			
Style/Code: Gant 15x21cm, Douche 70x130cm, Servt1 50x100cm, DB1 100x150cm					2880 pcs, DB1 1956 pcs			
Style/Code: Gant 15x21cm, Douc	ho 70	1×130cm 9	Sorve		Declared Qty. Gant 3036pcs 11ctn, Douche 1908			
50x100cm, DB1 100x150cm	ile /	ox iouciii, k	JEI V					
Sux roucili, DBT roux rsucili					pcs 106, Servt1 2880 pcs 80, DB1 1956 pcs 163ctn (Total 9780 pcs 360ctns)			
					,			
Learnestica Tura Derferend I FDI /Fin		-l :	4:\		status: 100% packed			
Inspection Type Performed: FRI (Fin			tion)	In	nspection Date: 09 March, 2007.			
Inspection Location: AT supplier's Fa								
INSPECTION CONCLUSION (In com	npariso				ction & reference sample, as available)			
		Conform		Vot				
			Cor	<u>nform</u>				
Quantities submitted for inspection:		<u> </u>			As per advised by Buyer			
Style, material, color:		V			As per ref. sample provided by Buyer			
Workmanship appearance/functioning	ng:	\checkmark			AQL 1.5 Level II			
Packing:		\checkmark			As per advised by Buyer			
Marking/label:		V						
Measurements/field tests :					Actual measurement sheets attached			
Constal about the constant	•		,					
General observation:								
Reservation :		·						
OVER ALL INSPECTION CONCLUSION.		□ CO	NEO	D.N.4	□ NOT CONFORM			
OVERALL INSPECTION CONCLUSION:		☑ <u>co</u>	NFO	<u>KIVI</u>	□ NOT CONFORM			
Follow up action: (as applicable)								
() Inspection certified will be issued								
oxdot Inspection certified will be issued after								
() Additional services: () Loading sup	pervisio	on () Stuffin	g sup	ervisio	on () Testing () others			
Samples drawn by :								
For Lob tooting.		For C	liont .		Cooled at factory			
					Sealed at factory :			
Of reason for not taking samples.								
INSPECTION METHOD APPLIED:								
ANSI / ASQC Z1.4-1993, Single sampling	g plan (Or: AQL 1.5 I	_evel	II (Nor	rmal inspection level)			
	51			•				
Acceptable Quality Level(AQL) for: Critical	al: <u>Nil</u>	Major:	07	N	Minor: Nil Sample size: 200 pcs			
Sample Selection formula: Square root	t basis	No. of Carto	ons/R	olls/Ba	ales Selected: 20 cartons			
Samples selected from package numbers	·:							



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon,

HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786

info@asiatextileinspections.com www.asiatextileinspections.com

Date:	Report Numb	Report Number:			Page 2 of 4			
1.PRODUCT CONFORMITY:								
1.1 Style Conformity:	☑ yes	□no	[]] no reference s	ample / specific	ation avai	ilable	
1.2 Material Conformity:	⊡ yes	□no		no reference sample / specification available				
•	•							
·	1.3 Color Conformity:				[] no reference sample / specification available			
Reference sample provided ☑ from principal				from manufacturer				
	from supplie	er		not a	vailable (explan	ation if ne	cessary)	
2. WORKMANSHIP APPEARANC	E / FUNCTION INSF	PECTION FI	NDING	S:		_		
Defective sampl	es	Critica	I	Major	Minor			
Yarn Peeling				01				
	Total Defectives :			01				
N			07	10				
Requested AQL								
Critical defective maximum allo	wed] Within AC	L Fo	ound 🔲 b	eyond AQL			
Major defective maximum allow	red <u>07</u> ☑	Within AQ	L Fo	ound <u>01</u> 🔲 b	eyond AQL			
Minor defective maximum allowed 10 ☑ Within AQL Found 0 ☐ beyond AQL								
Reservation:								
3. PRODUCT-SPECIFIC CHECKS ON REDUCED SAMPLE SIZE (as applicable for specific product / order)								
Size measurement on20	pcs sub-samp	les:	☐ yes	□ no ☑	actual finding (03 sheets	attached)	
Measurement Point	Size Ref. Sa	mple	Spec.	Tolerance	Deviation/	Finding	Sample(s)	

4. PACKING:

Each piece folded than packed in poly bag such 06 pcs(Gant), 01pc(Douche), 02 pcs(Servt1) and 01 pc(DB1) packed in cardboard

Carton Than wrapped with scoth tape.



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon,

485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

Date:	R	eport Numbe	er:	Page 3 of	[:] 4
4.1. Individual packing Confor	mity :	☑ yes	□no	(١
	ility .	•	_		
4.2. Inner packing conformity:		☑ yes	□ no	(
4.3. Export packing conformity :		☑ yes	no)
4.4. Packing assortment ' Che					
Carton No.	Carton No. Size/ Style		Colour	Deviation(+ / - samples)	_
5. MARKING / LABEL :					
Actual shipping Marks(if ship	ping mark	s not provide	ed in advance)		
SAIGON EPONGE GANT 10 VERT Commande of 100 453 COLIS N' 1/	BAIGON DB1 19 VERT	OTE 12	SAIGON EPONGE DOUCH 10 VERT Q LLT Commands COLIS N		,
5.1. Bar code conformity	☑ yes	☐ no		(•
5.2. Shipping mark conformity:	yes	☐ no		()
5.3. Other marks:	ges	☐ no		()
5.3.1 Side mark conformity:	ges	☑ no		()
5.3.2 Main label:	yes	☑ no		()
5.3.3 Care label:	ges	☑ no		()
5.3.4 Composition label:	ges	☑ no		()
5.3.5 Size label	ges	☑ no		()
5.3.6 Country origin label:	ges	☑ no		()
5.3.7 Hangtag:	☑ yes	☐ no		()
5.3.8 Polybag printing/ label:	☑ yes	no		()
5.3.9 Inner box printing / label:	ges	☑ no		()
5.3.10 Other Label	ges	☑ no		()



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

Date:	Report Number:				
6. INFORMATIVE O Inspection Environ					
Lighting:	☐ Daylight	☑ Room lighting	☑ Sufficient ☐ Insufficient ☐ Other :		
Inspection place:	☑Factory workshop:	Warehouse	☐ Others :		
Inspection done on:	☑ Table	☐ Top of cartons	☐ Others :		
Cleanliness:		Dirty	Others :		
Weather condition:	Rainy	☑ Dry	☐ Others :		
7. LOADING SUPER	RVISION:				
	Performed on	☑ Schedule for (after E			
A	TI Seal no.:				
8. ATTACHMENTS I	Photo report.				